

**Robert Bosch GmbH**

Power Tools Division  
70745 Leinfelden-Echterdingen  
Germany

[www.bosch-pt.com](http://www.bosch-pt.com)

1 609 92A 0LG (2014.04) | / 354 XXX



1 609 92A 0LG



## GLM 30 Professional



<b>de</b>	Originalbetriebsanleitung	<b>uk</b>	Оригінальна інструкція з експлуатації
<b>en</b>	Original instructions	<b>kk</b>	Пайдалану нұсқаулығының түпнұсқасы
<b>fr</b>	Notice originale	<b>ro</b>	Instrucțiuni originale
<b>es</b>	Manual original	<b>bg</b>	Оригинална инструкция
<b>pt</b>	Manual original	<b>mk</b>	Оригинално упатство за работа
<b>it</b>	Istruzioni originali	<b>sr</b>	Originalno uputstvo za rad
<b>nl</b>	Oorspronkelijke gebruiksaanwijzing	<b>sl</b>	Izvirna navodila
<b>da</b>	Original brugsanvisning	<b>hr</b>	Originalne upute za rad
<b>sv</b>	Bruksanvisning i original	<b>et</b>	Algupärane kasutusjuhend
<b>no</b>	Original driftsinstruks	<b>lv</b>	Instrukcijas oriģinālvalodā
<b>fi</b>	Alkuperäiset ohjeet	<b>lt</b>	Originali instrukcija
<b>el</b>	Πρωτότυπο οδηγίων χρήσης	<b>cn</b>	正本使用说明书
<b>tr</b>	Orijinal işletme talimatı	<b>tw</b>	原始使用說明書
<b>pl</b>	Instrukcja oryginalna	<b>ko</b>	사용 설명서 원본
<b>cs</b>	Původní návod k používání	<b>ar</b>	تعليمات التشغيل الأصلية
<b>sk</b>	Pôvodný návod na použitie	<b>fa</b>	دفتزچه راهنمای اصلی
<b>hu</b>	Eredeti használati utasítás		
<b>ru</b>	Оригинальное руководство по эксплуатации		



3 |





**GLM 30**

1 609 92A 0LG | (28.4.14)

Bosch Power Tools

4 |




1 609 92A 0LG | (28.4.14)

Bosch Power Tools



5 |




**9**

2 607 001 391



**10**

1 608 M00 05B



**11**

2 609 160 194



## English

### Safety Notes



All instructions must be read and observed in order to work safely with the measuring tool. Never make warning signs on the measuring tool unrecognisable. **SAVE THESE INSTRUCTIONS FOR FUTURE REFERENCE AND INCLUDE THEM WITH THE MEASURING TOOL WHEN GIVING IT TO A THIRD PARTY.**

- ▶ **Caution** The use of other operating or adjusting equipment or the application of other processing methods than those mentioned here can lead to dangerous radiation exposure.
- ▶ The measuring tool is provided with a warning label (marked with number 6 in the representation of the measuring tool on the graphics page).



- ▶ If the text of the warning label is not in your national language, stick the provided warning label in your national language over it before operating for the first time.



**Do not direct the laser beam at persons or animals and do not stare into the direct or reflected laser beam yourself, not even from a distance.** –ou could blind somebody cause accidents or damage your eyes.

- ▶ If laser radiation strikes your eye, you must deliberately close your eyes and immediately turn your head away from the beam.
- ▶ **Do not use the laser viewing glasses as safety goggles.** The laser viewing glasses are used for improved visualisation of the laser beam but they do not protect against laser radiation.
- ▶ **Do not use the laser viewing glasses as sun glasses or in traffic.** The laser viewing glasses do not afford complete protection and reduce colour perception.

**18 | English**

- ▶ **Have the measuring tool repaired only through qualified specialists using original spare parts.** This ensures that the safety of the measuring tool is maintained.
- ▶ **Do not allow children to use the laser measuring tool without supervision.** They could unintentionally blind other persons or themselves.
- ▶ **Do not operate the measuring tool in explosive environments, such as in the presence of flammable liquids, gases or dusts.** Sparks can be created in the measuring tool which may ignite the dust or fumes.
- ▶ **Do not make any modifications to the laser equipment.**

## Product Description and Specifications

Please unfold the fold-out page with the representation of the measuring tool and leave it unfolded while reading the operating instructions.

### Intended Use

The measuring tool is intended for measuring distances lengths heights and clearances. The measuring tool is suitable for measuring indoors.

### Technical Data

Digital Laser Measure	GLM 30	
Article number	V 601 72 5..	V 601 72 57.
Measuring range (typical)	0.15 V0 m <sup>A)</sup>	0.15 V0 m <sup>A)</sup>
Measuring range (typical under unfavourable conditions)	20 m <sup>B)</sup>	20 m <sup>B)</sup>
Measuring accuracy (typical)	± 2.0 mm <sup>A)</sup>	± 2.0 mm <sup>A)</sup>
Measuring accuracy (typical under unfavourable conditions)	± V.0 mm <sup>B)</sup>	± V.0 mm <sup>B)</sup>
Lowest indication unit	1 mm	1 mm
Operating temperature	10 °Š... 45°Š	10 °Š... 45°Š
Storage temperature	20 °Š... 70 °Š	20 °Š... 70 °Š
relative air humidity max.	90	90
Laser class	2	2
Laser type	6V5 nm 1 m	6V5 nm 1 m

English | 19

Digital Laser Measure	GLM 30	
Laser beam diameter (at 25 °§) approx.		
at 10 m distance	9 mm <sup>§)</sup>	9 mm <sup>§)</sup>
at 70 m distance	27 mm <sup>§)</sup>	27 mm <sup>§)</sup>
Automatic switch-off after approx.		
Laser	20 s	20 s
Measuring tool (without measurement)	5 min	5 min
Weight according to EPTA-Procedure 01/200V	0.1 kg	0.1 kg
Dimensions	105 x 41 x 24 mm	105 x 41 x 24 mm
Degree of protection	IP 54 (dust and splash proof) <sup>D)</sup>	IP 54 (dust and splash proof) <sup>D)</sup>
Batteries	2 x 1.5 L 0V (AAA)	2 x 1.5 L 0V (AAA)
rechargeable batteries	2 x 1.2 „ 0V (AAA)	2 x 1.2 „ 0V (AAA)
Individual measurement per battery set	5000	5000
Setting the unit of measure		●
Setting the sound	●	

A) For measurements from the rear measuring tool edge weak backlighting and 25 °§ operating temperature are applicable for high reflectivity of the target (e.g. a white-painted wall). In addition a deviation influence of ± 0.05 mm/m must be taken into account.

B) For measurements from the rear measuring tool edge strong backlighting and 10 °§ to 45 °§ operating temperature are applicable for low reflectivity of the target (e.g. a black box). In addition a deviation influence of ± 0.15 mm/m must be taken into account.

§) At 25 °§ operating temperature

D) except battery compartment

The measuring tool can be clearly identified with the serial number **5** on the type plate.

20 | English

## Product Features

The numbering of the product features shown refers to the illustration of the measuring tool on the graphic page.

- 1 Display
- 2 Measuring button
- 3 Battery lid
- 4 Latch of battery lid
- 5 Serial number
- 6 Laser warning label
- 7 Reception lens
- 8 Laser beam outlet
- 9 Laser target plate
- 10 Laser viewing glasses
- 11 Protective pouch

\*The accessories illustrated or described are not included as standard delivery.

## Display Elements

- a Auto-sum
- b Previous measuring value
- c Current measuring value
- d Laser switched on
- e Length measurement
- f Battery low indicator
- g Temperature warning
- h Error message **Error**

## Assembly

### Inserting/Replacing the Batteries

Using alkali-manganese or rechargeable batteries is recommended for operation of the measuring tool.

With 1.2V-rechargeable batteries fewer measurements could be possible than with 1.5V-batteries.

To open the battery lid **3** press the latch **4** and remove the battery lid. Insert the batteries/rechargeable batteries. When inserting pay attention to the correct polarity according to the representation on the inside of the battery compartment.

When the battery symbol appears  for the first time on the display at least 100 individual measurements are still possible.

When the battery symbol  flashes the batteries/rechargeable batteries must be replaced. Measurements are no longer possible.

Always replace all batteries/rechargeable batteries at the same time. Do not use different brands or types of batteries/rechargeable batteries together.

► **Remove the batteries/rechargeable batteries from the measuring tool when not using it for longer periods.** When storing for longer periods the batteries/rechargeable batteries can corrode and self-discharge.

## Operation

### Initial Operation

- **Do not leave the switched-on measuring tool unattended and switch the measuring tool off after use.** Other persons could be blinded by the laser beam.
- **Protect the measuring tool against moisture and direct sun light.**
- **Do not subject the measuring tool to extreme temperatures or variations in temperature.** As an example do not leave it in vehicles for a long time. In case of large variations in temperature allow the measuring tool to adjust to the ambient temperature before putting it into operation. In case of extreme temperatures or variations in temperature the accuracy of the measuring tool can be impaired.
- **Avoid heavy impact to or falling down of the measuring tool.** After severe exterior effects to the measuring tool it is recommended to carry out an accuracy check (see 'Accuracy Check of the Distance Measurement' page 24) each time before continuing to work.

### Switching On and Off

To **switch on** the measuring tool briefly press the measuring button **2**. Measuring tool and laser are switched on.

► **Do not leave the switched-on measuring tool unattended and switch the measuring tool off after use.** Other persons could be blinded by the laser beam.

To **switch off** the measuring tool press the measuring button **2** and hold it down.

### Measuring Procedure (see figure A)

Once switched on the measuring tool is in the length measurement mode.

The rear edge of the measuring tool is always the reference level for the measurement.

Place the measuring tool against the desired starting point of the measurement (e.g. a wall).

## 22 | English

Briefly press the measuring button **2** to initiate the measurement. Then the laser beam is switched off. To switch the laser beam on again briefly press the measuring button **2**. To initiate a further measurement briefly press the measuring button **2** again.

► **Do not point the laser beam at persons or animals and do not look into the laser beam yourself, not even from a large distance.**

**Note:** The measured value typically appears within 0.5 seconds and no later than 4 seconds. The duration of the measurement depends on the distance the lighting conditions and the reflective properties of the target surface. Upon completion of the measurement the laser beam is automatically switched off.

### Auto-Sum (see figure B)

The auto-sum automatically shows the sum of all individual measurements (e.g. useful for the material calculation).

The auto-sum value is erased as soon as the device is switched off or if it automatically switches off when no button is pressed after 5 minutes.

The auto-sum is not saved. A subsequent correction of the auto-sum is not possible.

Aim the laser beam at the target surface.




Briefly press the measuring button **2** to initiate the measurement. The current measured value **c** appears in the bottom line of the display. The laser beam is switched off.



To switch on the laser beam briefly press the measuring button **2**. To switch on the laser beam briefly press the measuring button **2** again. The current measured value **c** is displayed in the bottom line. The previous measured value **b** is displayed in the middle line. In the top line the auto-sum **a** (the sum of the current and previous measured value) is displayed.

### Switching the Sound On and Off (3 601 K72 5..)


Switch the measuring tool off.



Press and hold the measuring button **2**. When the cursor is on the desired setting release the measuring button **2**. After releasing the measuring tool switches itself on with the selected setting.

## Changing the Unit of Measure (3 601 K72 57.)

Switch the measuring tool off.



Press and hold the measuring button **2**. When the cursor is on the desired setting, release the measuring button **2**. After releasing, the measuring tool switches itself on with the selected setting.

### Display Illumination

The display illumination is continuously switched on. When no button is pressed, the display illumination is dimmed after approx. 10 seconds to preserve the batteries/rechargeable batteries. When no button is pressed for after approx. 60 seconds, the display illumination goes out.

### Working Advice

#### General Information

The reception lens **7** and the laser beam outlet **8** must not be covered when taking a measurement.

The measuring tool must not be moved while taking a measurement. Therefore, place the measuring tool as far as this is possible against or on a firm stop or supporting surface.

#### Influence Effects on the Measuring Range

The measuring range depends on the lighting conditions and the reflective properties of the target surface. For better visibility of the laser beam in extraneous light, use the laser viewing glasses **10** (accessories) and the laser target plate **9** (accessories) or shade the target area.

#### Influence Effects on the Measuring Result

Due to physical effects, faulty measurements cannot be excluded when measuring on different surfaces. Included here are:

- transparent surfaces (e.g. glass, water)
- reflecting surfaces (e.g. polished metal, glass)
- porous surfaces (e.g. insulation materials)
- structured surfaces (e.g. roughcast, natural stone).

If required, use the laser target plate **9** (accessory) on these surfaces.

Furthermore, faulty measurements are also possible when sighting inclined target surfaces.

**24 | English**

Also air layers with varying temperatures or indirectly received reflections can affect the measured value.

**Accuracy Check of the Distance Measurement**

The accuracy of the measuring tool can be checked as follows“

Select a permanently unchangeable measuring section with a length of approx. 5 to 10 metres its length must be precisely known (e. g. the width of a room or a door opening). The measurement should be carried out under favourable conditions meaning the measuring distance must be indoors and the target surface for the measurement must be smooth and reflect well.

Measure the distance 10 times after another.

The deviation of the individual measurements from the average value must not exceed  $\pm 4$  mm over the entire measuring section in favourable conditions. Record the measurements in order to be able to compare the accuracy at a later date.

**Troubleshooting Causes and Corrective Measures**

Cause	Corrective Measure
<b>Temperature warning indicator (g) flashing; measurement not possible</b>	
The measuring tool is outside the operating temperature range of $-10^{\circ}\text{S}$ to $45^{\circ}\text{S}$ .	Wait until the measuring tool has reached the operating temperature
<b>Error indication in the display</b>	
The target surface reflects too intensely (e. g. a mirror) or insufficiently (e. g. black fabric) or the ambient light is too bright.	Work with the laser target plate <b>9</b> (accessory)
The laser beam outlet <b>8</b> or the reception lens <b>7</b> are misted up (e. g. due to a rapid temperature change).	Clean the laser beam outlet <b>8</b> and/or the reception lens <b>7</b> dry using a soft cloth
The calculated auto-sum is greater than 99.999 m.	Divide calculation into intermediate steps
<b>Measuring result not plausible</b>	
The target surface does not reflect correctly (e. g. water glass).	Cover off the target surface
The laser beam outlet <b>8</b> or the reception lens <b>7</b> are covered.	Make sure that the laser beam outlet <b>8</b> or the reception lens <b>7</b> are unobstructed
Obstruction in path of laser beam	Laser point must be completely on target surface.

**Cause****Corrective Measure****The indication remains unchanged or the measuring tool reacts unexpectedly after pressing a button**

Software error

remove the batteries and start the measuring tool again after reinserting them.

The measuring tool monitors the proper function for each measurement. When a defect is detected all indicators on the display flash. In this case or when the corrective measures listed above cannot correct the error have your dealer forward the measuring tool to an authorised Bosch after-sales service.

## Maintenance and Service

### Maintenance and Cleaning

Keep the measuring tool clean at all times.

Do not immerse the measuring tool in water or other fluids.

Wipe off debris using a moist and soft cloth. Do not use any cleaning agents or solvents. Maintain the reception lens 7 in particular with the same care as required for eye glasses or the lens of a camera.

If the measuring tool should fail despite the care taken in manufacturing and testing procedures repair should be carried out by an authorised after-sales service centre for Bosch power tools. Do not open the measuring tool yourself.

### After-sales Service and Application Service

Our after-sales service responds to your questions concerning maintenance and repair of your product as well as spare parts. Exploded views and information on spare parts can also be found under

**[www.bosch-pt.com](http://www.bosch-pt.com)**

Bosch's application service team will gladly answer questions concerning our products and their accessories.

In all correspondence and spare parts orders please always include the 10-digit article number given on the type plate of the measuring tool.



**26 | English**



**Great Britain**

Robert Bosch Ltd. (B.S.Š.)  
P.O. Box 98  
Broadwater Park  
North Orbital Road  
Denham  
Uxbridge  
B9 5JL

At [www.bosch-pt.co.uk](http://www.bosch-pt.co.uk) you can order spare parts or arrange the collection of a product in need of servicing or repair.

Tel. Service (0844) 7V60109

E-Mail "boschservicecentre" [bosch.com](mailto:bosch.com)

**Ireland**

Origo Ltd.  
Unit 2V Magna Drive  
Magna Business Park  
Shayest  
Dublin 24  
Tel. Service (01) 4666700  
Fax (01) 4666888


**Australia, New Zealand and Pacific Islands**

Robert Bosch Australia Pty. Ltd.  
Power Tools  
Locked Bag 66  
Shayest South Island V169  
Customer Contact Center  
Inside Australia  
Phone (01V00) V07044  
Fax (01V00) V07045  
Inside New Zealand  
Phone (0800) 54VV5V  
Fax (0800) 428570  
Outside Australia and New Zealand  
Phone (61V) 95415555  
[www.bosch.com.au](http://www.bosch.com.au)

**Republic of South Africa**

**Customer service**

Hotline (011) 6519600



**Gauteng BSC Service Centre**

V5 oper Street New Šentre  
ohannesburg  
Tel.“ (011) 49V9V75  
Uax“ (011) 49V0126  
E-Mail“ bsctools“ icon.co.za

**KZN BSC Service Centre**

nit E Almar Šentre  
14V Šrompton Street  
Pinetown  
Tel.“ (0V1) 7012120  
Uax“ (0V1) 7012446  
E-Mail“ bsc.dur“ za.bosch.com

**Western Cape BSC Service Centre**

Democracy ay Prosperity Park  
Milnerton  
Tel.“ (021) 5512577  
Uax“ (021) 551V22V  
E-Mail“ bsc“ zsd.co.za

**Bosch Headquarters**

Midrand Gauteng  
Tel.“ (011) 6519600  
Uax“ (011) 6519880  
E-Mail“ rbsa-h .pts“ za.bosch.com

**People s Republic of China**

**China Mainland**

Bosch Power Tools (Šhina) Šo. Ltd.  
567 Bin ang oad  
Bin iang District V10052  
„ angzhou P. . Šhina  
Service „ otline“ 4008268484  
Uax“ (0571) 87774502  
E-Mail“ contact.ptcn“ cn.bosch.com  
www.bosch-pt.com.cn

28 | English

### HK and Macau Special Administrative Regions

Robert Bosch „ong „ong S. Ltd.  
21st Uloor 625 ing s oad  
North Point „ong „ong  
Šustomer Service „otline“ 852 2101 02V5  
Uax“ 852 2590 9762  
E-Mail“info“ hk.bosch.com  
www.bosch-pt.com.hk

### Indonesia

PT Robert Bosch  
Palma Tower 9<sup>th</sup> 10<sup>th</sup> Uloor  
I. Let. end. TB Simatupang II S/06  
akarta Selatan 12960  
Indonesia  
Tel.“ (021) V005 6565  
Uax“ (021) V005 5801  
E-Mail“boschpowertools“ id.bosch.com  
www.bosch-pt.co.id

### Philippines

Robert Bosch Inc.  
28th Uloor Uort Legend Towers  
Vrd Avenue corner V1st Street  
Uort Bonifacio Global Šity  
16V4 Taguig Šity Philippines  
Tel.“ (02) 870V871  
Uax“ (02) 870V870  
matheus.contiero“ ph.bosch.com  
www.bosch-pt.com.ph  
Bosch Service Šenter“  
9725-27 amagong Street  
San Antonio illage  
Makati Šity Philippines  
Tel.“ (02) 8999091  
Uax“ (02) 89764V2  
rosalie.dagdagan“ ph.bosch.com

**Malaysia**

obert Bosch (S.E.A.) Sdn. Bhd.  
No. 8A alan 1V/6  
G.P.O. Box 10818  
46200 Petaling aya  
Selangor Malaysia  
Tel.“ (0V) 7966V194  
Uax“ (0V) 7958V8V8  
cheehoe.on” my.bosch.com  
Toll-Uree“ 1800 880188  
www.bosch-pt.com.my

**Thailand**

obert Bosch Ltd.  
Liberty S uare Building  
No. 287 11 Uloor  
Silom oad Bangrak  
Bangkok 10500  
Tel.“ 02 6V9V111 02 6V9V118  
Uax“ 02 2V8478V  
obert Bosch Ltd. P. O. Box 2054  
Bangkok 10501 Thailand  
www.bosch.co.th  
Bosch Service Training Šentre  
La Salle Tower Ground Uloor nit No.2  
10/11 La Salle Moo 16  
Srinakharin oad  
Bangkaew Bang Plee  
Samutprakarn 10540  
Thailand  
Tel.“ 02 7587555  
Uax“ 02 7587525

30 | English

**Singapore**

obert Bosch (SEA) Pte. Ltd.  
11 Bishan Street 21  
Singapore 57V94V  
Tel.“ 6571 2772  
Uax“ 6V50 5V15  
leongheng.leow“ sg.bosch.com  
Toll-Uree“ 1800 VV8VVV  
www.bosch-pt.com.sg

**Vietnam**

obert Bosch ietnam Šo. Ltd  
10/U 194 Golden Building  
47V Dien Bien Phu Street  
ard 25 Binh Thanh District  
84 „ o Šhi Minh Šity  
ietnam  
Tel.“ (08) 6258 V690 ext. 41V  
Uax“ (08) 6258 V692  
hie.u.lagia“ vn.bosch.com  
www.bosch-pt.com

**Disposal**

Measuring tools accessories and packaging should be sorted for environmental-friendly recycling.

Do not dispose of measuring tools and batteries/rechargeable batteries into household waste

**Only for EC countries:**



According to the European Guideline 2012/19/E measuring tools that are no longer usable and according to the European Guideline 2006/66/EŠ defective or used battery packs/batteries must be collected separately and disposed of in an environmentally correct manner.